

ATTACHMENT 5 – DEVIATIONS

Deviations

§60.5420(b)(2-4)(ii); (5-6)(iii) and §60.5420a(b)(2-4)(ii); (5-6)(iii)

Facility	Equipment Name	Explanation
Knob Fork Compressor Station	Engine #3	Rod Packing was not been replaced before 26,000 hrs. Scheduled to be replaced in November 2019.